


Cable assembly RF178-02SJ1-02SJ1-0305 (MCX to MCX).
See characterization report for more information.



Typical. Results may vary. Includes cable assembly RF178-02SJ1-02SJ1-0305 (MCX to MCX) and adaptor effects. See characterization report for more information.